

PERFORMANCE RADIATOR

Performance Radiator brings good news and an easy fix to owners of 1988 -1991 5.7L Chevrolet C/K pickups. The days of overheating problems are finished when replacing an under performing OE with a new Performance Radiator 622-84. No additional parts are required for Performance retrofit.

Performance Radiator proudly presents the latest technology in high performance core design AB36 on 622-84. Both wind tunnel test and actual road test have proven outperforming heat dissipation compared against OEM and any other manufacturers .

If we were GM, we would want to sell you 12 parts. However, only one is necessary. For those experienced with a widespread overheating problem with these vehicles, GM recommends retrofitting an original 28-inch OEM with a wider, 34-inch cross flow*1.



With a dozen retrofit parts, cutting and drilling to make room for the new radiator, the changeover can be a real waste of time, not to mention draining and refilling the radiator.

We can accomplish this by replacing the 28" stock radiator with the High Efficient Performance Radiator 622-84. Quality Engineering. Quality Fit. There is a Difference!

So, give your customers and yourself a break with a Performance Radiator 622-84!



1988 -1991 5.7L Chevrolet C/K pickups



Call in an Order Today!

Tacoma Carolanne 800-522-2446	Raliegh Bruce or Trinity 888-565-4801	Denver Rita or Tom 800-423-4473
Houston Kelly or Paula 800-950-0873	Reno Crystal or Paul 888-825-8250	Phoenix Brad or Dennis 800-949-1191

Quality...There is a Difference!